



# Harness inspection certificate - EN

Inspection certificate number: **PH 374.2022**

Impact pad number: **PH 374.2022**


### Manufacturer data

Manufacturer name: **Woody Valley srl**  
 Representative: **Simone Caldana**  
 Street: **Via Linz 23**  
 Post code / place: **38121 Trento**  
 Country: **Italy**

Sample data:	Harness	Impact pad
Name:	<b>MK1 Pro</b>	Name Impact pad: <sup>(1)</sup> <b>n/a</b>
Type:	<b>ABS</b>	Impact pad integrated: <sup>(1)</sup> <b>No</b>
Size:	<b>M</b>	Impact pad type: <b>Foam</b>
Weight of Sample [kg]:	<b>7.76</b>	Weight of Sample [kg]: <sup>(1)</sup> <b>0.96</b>
Serial number:	<b>107 0115 002P</b>	Serial number: <sup>(1)</sup> <b>107 0115 002P</b>
Clip-in weight [kg]:	<b>120</b>	
Integrated container for rescue system:	<b>Yes</b>	Date of reception: <b>07.09.2022</b>
Volume container [cm <sup>3</sup> ]:	<b>10000</b> max <b>5000</b> min	
Date of reception:	<b>01.02.2022</b>	

Test report summary	Structual test	Impact pad test
Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	09.03.2022	07.09.2022

### Issue data

Place of declaration: Villeneuve  
Date of issue: 03.11.2022  
Managing Director: Andrea Wigger  
Signature: 

**The Base System is not covered by this certificate**

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)

**Air Turquoise SA**, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651:2018** and **EN12491:2015**

(1) If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22