

Harness inspection certificate - EN

Inspection certificate number: **PH_378.2022**Impact pad number: **n/a**

Manufacturer data

Manufacturer name: **Woody Valley srl**
 Representative: **Simone Caldana**
 Street: **Via Linz 23**
 Post code / place: **38121 Trento**
 Country: **Italy**

Sample data:

Harness

Impact pad

Name:	DENALI	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	n/a
Size:	M	Impact pad type:	n/a
Weight of Sample [kg]:	0.26	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	111 0115 001P	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	n/a
Integrated container for rescue system:	No		
Volume container [cm ³]:			n/a max n/a min
Date of reception:	18.10.2022		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	n/a
Place	Villeneuve	n/a
Date	18.10.2022	n/a

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **25.10.2022**
 Managing Director: **Andrea Wigger**
 Signature: 

This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)
 Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:
EN1651:2018+A1:2020⁽²⁾ and EN12491:2015+A1:2021⁽²⁾

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag

⁽²⁾ These standards are NOT covered by accreditation D-IS-19457-01

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22
 The declaration must not be reproduced in part without the written permission of Air Turquoise SA